



EXPOSED STEEL  
BEAMS ABOVE

HATCHING INDICATES  
REDUCED CEILING HEIGHT  
ABOVE AT RAMP FLOOR